

TWI NON-ROUTINE SAMPLE REPORT

RECEIVER #: _____

PROFILE #: _____

GENERATOR: UES/TWI Superfund MP-1 Truck Slot

SAMPLE #	ANALYSIS	RESULT (mg/kg)	DATE	ANALYST
<u>101212-C</u>	As by ICP	<u><5.0</u>	<u>10/16/12</u>	<u>NF</u>
	Be by ICP	<u><0.1</u>		
	Cd by ICP	<u><1.0</u>		
	Cr by ICP	<u><2.5</u>		
	Pb by ICP	<u><2.5</u>		
	Hg by DMA-80	<u><0.04 By Dur</u>		

REVIEWED BY: _____

DATE: 10/31/12

THIS SAMPLE WAS COLLECTED ACCORDING TO APPLICABLE SW-846 PROCEDURES

This report had been prepared for the exclusive use and benefit of Veolia Environmental Services.

No representation concerning sample validity or analytical accuracy of completeness is hereby made to any other person receiving this report.

TWI NON-ROUTINE SAMPLE REPORT

RECEIVER #: _____

PROFILE #: _____

GENERATOR: WESTWI Samp Water MP-1 Truck Slot

SAMPLE #	ANALYSIS	RESULT (mg/kg)	DATE	ANALYST
<u>101212-D</u>	As by ICP	<u>< 50</u>	<u>10/16/12</u>	<u>NF</u>
	Be by ICP	<u>< 0.1</u>		
	Cd by ICP	<u>< 1.0</u>		
	Cr by ICP	<u>< 2.5</u>		
	Pb by ICP	<u>< 2.5</u>		
	Hg by DMA-80	<u>< 0.04</u>		

REVIEWED BY: _____

DATE: _____

THIS SAMPLE WAS COLLECTED ACCORDING TO APPLICABLE SW-846 PROCEDURES

This report had been prepared for the exclusive use and benefit of Veolia Environmental Services.

No representation concerning sample validity or analytical accuracy or completeness is hereby made to any other person receiving this report.

REPORT TO: _____

TWI NON-ROUTINE SAMPLE REPORT

RECIEVER #: SUMPWATER

PROFILE #: _____

GENERATOR: VES Sump Water #3

DRUM #: _____

3/6/13

SAMPLE #	ANALYSIS	RESULT (mg/kg)	DATE	ANALYST
<u>030613-B</u>	<u>As by ICP</u>	<u><5.0</u>	<u>3/7/13</u>	<u>RWH</u>
	<u>Be by ICP</u>	<u><0.1</u>		
	<u>Cd by ICP</u>	<u><1.0</u>		
	<u>Cr by ICP</u>	<u><2.5</u>		
	<u>Pb by ICP</u>	<u><2.5</u>		
	<u>Hg by DMA-80</u>	<u><0.04</u>		

REVIEWED BY: [Signature]DATE: 3/8/13

THIS SAMPLE WAS COLLECTED ACCORDING TO APPLICABLE SW-846 PROCEDURES

This report had been prepared for the exclusive use and benefit of Veolia Environmental Services.

No representation concerning sample validity or analytical accuracy of completeness is hereby made to any other person receiving this report.

REPORT TO: _____

TWI NON-ROUTINE SAMPLE REPORT

RECIEVER #: SUMPWATER

PROFILE #: _____

GENERATOR: VES / Sump Water #3
3/6/13

DRUM #: _____

SAMPLE #	ANALYSIS	RESULT (mg/kg)	DATE	ANALYST
<u>030613-D</u>	<u>As by ICP</u>	<u><5.0</u>	<u>3/7/13</u>	<u>rust</u>
	<u>Be by ICP</u>	<u><0.1</u>		
	<u>Cd by ICP</u>	<u><1.0</u>		
	<u>Cr by ICP</u>	<u><2.5</u>		
	<u>Pb by ICP</u>	<u><2.5</u>		
	<u>Hg by DMA-80</u>	<u><0.04</u>		

REVIEWED BY: DATE: 3/8/13

THIS SAMPLE WAS COLLECTED ACCORDING TO APPLICABLE SW-846 PROCEDURES

This report had been prepared for the exclusive use and benefit of Veolia Environmental Services.

No representation concerning sample validity or analytical accuracy or completeness is hereby made to any other person receiving this report.

REPORT TO: _____

TWI NON-ROUTINE SAMPLE REPORT

RECEIVER #: SUMPWATER

PROFILE #: _____

GENERATOR: VES Sump Water # 3
3/6/13

DRUM #: _____

SAMPLE #	ANALYSIS	RESULT (mg/kg)	DATE	ANALYST
<u>030613-C</u>	<u>As by ICP</u>	<u><5.0</u>	<u>8-3-13</u>	<u>WJA</u>
	<u>Be by ICP</u>	<u><0.1</u>		
	<u>Cd by ICP</u>	<u><1.0</u>		
	<u>Cr by ICP</u>	<u><2.5</u>		
	<u>Pb by ICP</u>	<u><2.5</u>		
	<u>Hg by DMA-80</u>	<u><0.04</u>		

REVIEWED BY: DATE: 3-8-13

THIS SAMPLE WAS COLLECTED ACCORDING TO APPLICABLE SW-846 PROCEDURES

This report had been prepared for the exclusive use and benefit of Veolia Environmental Services.

No representation concerning sample validity or analytical accuracy of completeness is hereby made to any other person receiving this report.